| SUPERFUND SITE STRATEGY RECOMMENDATION (S | |
|--|--|
| Site Name: US Navy McGregor Naval Weapons | Site Number: <u>TX4570090007</u> |
| Alias Site Name(s): | |
| Address: 101 Johnson Drive | |
| City/County or Parish/State/Zip: McGregor/unknow | vn/TX/76657 |
| RECOMMENDATION: | |
| 1. No further remedial action planned under Su | perfund. |
| $\{X\}$ 2. Further pre-remedial investigative action no | eeded under Superfund. |
| | /: High Low X |
| SSI LSI Other PREscore To be performed by ARCS | |
| 3. Action may be appropriate under other authorn NPDES SPCC TSCA State Other | rity: RCRA UIC SMCRA |
| Discussion: A Confirmation Study and Evaluation of Remedial Alternatives Report dated July 1985 was reviewed for this facility. The facility has been in operation since 1942. | |
| Soil and ground water contamination had pesticides such as DDT, toxaphene, and ben | occurred primarily from zene hexachloride (BHC). |
| Remedial action including the removal of soil, the draining and filling of two impoundments and the surveillance of monitoring wells has occurred on site. | |
| To comprehensively evaluate the status of the facility, a HRS Prescore should be performed following the current EPA guidelines. The Prescore should identify the data gaps present and those areas of the site needing further evaluation, if necessary. | |
| | SUPERFUND FILE |
| EM 15 PER SECOND | JAN 1 2 1993 |
| | REORGANIZED |
| Copies to (please list): 6E-FF 6E-E, NMED, ATSDR, 6W-SP | |
| 2 2 10 | Date: 4/27/44 |
| | Date: 4/23/92 Date: 4/29/92 |